

CONTINUATION SHEET	Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-P-0159 MOD/AMD P00001	Page 3 of 4
Name of Offeror or Contractor: KOLLMORGEN CORPORATION		

DESCRIPTION/SPECIFICATIONS/WORK STATEMENT

SCOPE OF WORK

A. The following Scope of Work is hereby in effect for the repair/rework of the item described below:

NOMENCLATURE: Travel Lock Actuator WITH CONTAINER
QUANTITY: 64
NSN: 3010-01-373-5945
MILITARY PART NUMBER: 57K3244
KOLLMORGEN PART NUMBER: 12361513

- The contractor shall perform warranty inspection for failure due to RTV-108 and/or leakage path, complete warranty repairs at no cost and return the repaired units to New Cumberland Army Depot.
- The contractor shall perform repair analysis on the remaining units to identify the quantity which can be repaired and the extent of rework required.
- The contractor shall complete rework of reparable units and return these units to New Cumberland Army Depot. Each rework effort shall fall into one of three categories:

Category 1: This rework will cover necessary replacement of parts, including the switches, hardware, O-rings, seal, clutch and brake. The price for rework in this category is \$925.00.

Category 2: This rework will cover necessssary replacement of parts, including the switches, hardware, O-rings, seal, clutch, brake, lock nut and ball nut assembly. The price for rework in this category is \$1,495.00.

Category 3: This rework shall cover necessary replacement of parts, including the switches, hardware, O-rings, seal, clutch, brake, ball nut assembly, motor components (rotor assembly, stator assembly, brush ring assembly), bearings and connector. The price for rework in this category is \$3,810.00.
- In addition to the replacement of components, rework will include disassembly to the extent necessary, cleaning and degreasing of actuator components, setting/adjustment of the clutch assembly and the stroke, reassembly, testing, painting, marking and inspecting the actuator.
- The contractor shall list the components being replaced for each repair.
- The contractor shall notify the Government of the results of the evaluation and proceed immediately to rework the item.
- Units identified as damaged beyond repair shall be scrapped in accordance with Government procedures. At the conclusion of the repair analysis, an evaluation fee of \$300.00 shall be paid to the contractor for each unit deemed uneconomical to repair.
- Should units to be repaired remain at the contractor's facility once the total value of the contract has been exhausted, the Government shall provide additional funding or instructions to return the unrepaired parts within 30 days after receiving written notification from the contractor. Otherwise, a storage fee of \$100 per day/per part will be charged.

9. The following "SHIP TO" and "MARK FOR" designations are applicable to this Purchase Order:

SHIP TO: XR W390 RED RIVER MUNITIONS CENTER
HIGHWAY 82 WEST, CL V, TPF
GATE 44, BLDG 184
TEXARKANA, TX 75507-5000

MARK FOR: TACOM (AKZ) MISSION STOCK
D6M RETURN FROM REPAIR
CONDITION CODE "A"
DCN: W56HZV4012Z161

CONTINUATION SHEET	Reference No. of Document Being Continued PIIN/SIIN W56HZV-04-P-0159 MOD/AMD P00001	Page 4 of 4
Name of Offeror or Contractor: KOLLMORGEN CORPORATION		

B. Total funding reflected on this Purchase Order also includes a lot charge of \$500.00 for the evaluation, paint touch-up and retesting of an additional seven (7) actuators.

*** END OF NARRATIVE C 001 ***